

PT. Permata Industri Jaya Abadi

JL. Panglima Polim Raya no 93, Melawai, Kebayoran Baru.
Jakarta 12160 Indonesia.

Phone no: +62 21 7392434, Fax no: +62 21 7392526

Email: office@permataindustrijiyaabadi.co.id

TRIAL REPORT

❖ SUBJECT	: Thompson Coupling - type TCAE-1
➤	DBSE min/max 80/85 mm, Max Power@ 1440rpm 15/22 kw/Hp, Max speed 3500 rpm, Max Angle 5 degree, Minimum Angle 1 degree, Max Temperature :120 deg C.
❖ Location	: PT. Pindo Deli pulp and paper Tbk. / Kerawang mill
	▪ PM9, Condensate Pump no.5
❖ Dated	: 16/08/2016
❖ Problems categorize	
	<ul style="list-style-type: none">• High vibration• Parts failures• Misalignment• Area and machines conditions cause very hard to offer suitable alignment process.

Replacement process



PT. Permata Industri Jaya Abadi

JL. Panglima Polim Raya no 93, Melawai, Kebayoran Baru.
Jakarta 12160 Indonesia.

Phone no: +62 21 7392434, Fax no: +62 21 7392526

Email: office@permataindustrijayaabadi.co.id

Installation process done



Monitoring and Result.

Report measuring vibration				
Loc	Pindo 2			
Area	PM 9			
Machine	Condensat Pump no.5			
Type Coupling	TCAE-1			
Install date	16/08/2016			
	Before using thompson coupling		After using thompson coupling	
Measuring date	2/8/2016		2/9/2016	
From	MTS Team		MTS Team	Vibration lower by %
motor outboard vertical / M1V	1.434	mm/sec	1.181	18
motor inboard horizontal / M2H	3.353	mm/sec	2.87	14
motor inboard vertical / M2V	3.347	mm/sec	2.153	36
motor inboard axial / M2A	3.308	mm/sec	2.623	21
inboard pump horizontal / P1H	5.048	mm/sec	3.631	28
inboard pump vertical / P1V	5.057	mm/sec	2.281	55
inboard pump axial / P1A	4.924	mm/sec	2.502	49
outboard pump horizontal / P2H	3.892	mm/sec	2.408	38
outboard pump vertical / P2V	3.845	mm/sec	2.404	37
outboard pump axial / P2A	3.88	mm/sec	1.931	50

Advantages

- ❖ NO Alignment process involve during the installation – faster time!
- ❖ Proven, able to minor vibration (more than 50%) due to misalign machineries
- ❖ Prologue life time for the machines
- ❖ Cut down unscheduled maintenance process and parts failure.
- ❖ Optimize production time
- ❖ Coupling warranty for 1 year.